



Flue Crew Chimney Services

Store: 705-653-0111 Cell: 705-653-6564 Email: fluecrew@gmail.com
49 Trent Drive Campbellford, Ontario K0L 1L0

Rob Beck W.E.T.T. #8989 We are fully insured.



Invoice / Receipt / Estimate Number: 2024 993

Submitted To: SHAWNNE SPENCER

Phone: 613 848 6769

Address: 77 BAYSHORE RD, PRESQUILLE

City: BRIGHTON, ON

Date: JUNE 11 2024

Parts / Supplies

Labour / Other

Description	Qty	Unit Cost	Amount	
REQUIREMENTS:				VISUAL INSPECTION OF
				MASONRY/STONE FIREPLACE +
1- FLOOR AREA MUST				WOOD BURNING INSERT.
BE A MINIMUM OF				
18" CONTINUOUS NON-				APPEARS IN GOOD & SOUND
COMBUSTIBLE MATERIALS.				CONDITION (INSERT & STONE FIRE-
IT IS CARPET AT THIS				PLACE)
TIME.				
				CHIMNEY IS ENCLOSED ON ROOF
2- WOOD MANTLE				TOP & NOT VISIBLE FOR INSPECTION
UGHT TO BE				WITHIN METAL SHROUD, IT
SHIELDED WITH METAL				APPEARS TO BE IN GOOD/SOUND
& APPROPRIATE AIR				CONDITION)
SPACE OF $\frac{7}{8}$ " MINIMUM				
AND APPROXIMATELY				PAID IN FULL CNG
54" WIDE X 8" PROJECTION				
($8 + \frac{1}{2} + 1 = 9 \frac{1}{2}$ " CUT SIZE)				
Total Parts				Total Labour

Building permit is client's responsibility. All prices subject to pre-inspection. All materials remain property of Flue Crew Chimney Services until paid in full. Payment in full is due on completion of work contracted.

HST # 851743807RT0001

Subtotal Parts & Labour: 115.-

H.S.T. 14.95

TOTAL: 129.95

Guarantee: All workmanship is guaranteed for three years from the completion date unless otherwise stated. Every attempt has been made to assess the materials and time needed to make the installation compliant. Some hidden conditions may cause changes to the estimate. Changes to the estimate will be discussed with you before further work commences.

Signature: _____

Date: _____

W.E.T.T. Certified Sweeping, Inspections, Installations, Relining, Masonry Repairs and Parts.

705-653-6564